


VISITATION TEAM - EXIT SUMMARY
School: Gustine Elementary

Date of Visit: Tuesday, August 16, 2016

Principal: Lisa Filippini

Fall of 2016

Total Enrollment: 565

MCOE Lead: Michelle Symes

Total Classrooms: 26

MCOE Team: Stacy Shasky
 Ray Birch

Actual Classes Visited: 8

Other Facilities Visited: Restrooms
 Office
 Multi-Purpose
 Teacher Lounge

Was there textbook sufficiency?
Language Arts: Yes

Science: Yes

Health: No

Mathematics: Yes

Science Lab: No

Foreign Language: No

Social Studies: Yes

Instructional Materials Notes

Room B1/TK 23 books missing for ELA/History/Science.

Emergency Insufficiencies No
SARC Posted on Web Yes
Exit Meeting Yes
Current SARC Yes
Follow Up Needed Yes
UCP in All Classrooms Yes
Facilities Notes

See FIT.

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION GUSTINE UNIFIED SCHOOL DISTRICT.		COUNTY MERCED
SCHOOL SITE GUSTINE ELEMENTARY		SCHOOL TYPE (GRADE LEVELS) TK-5
INSPECTOR'S NAME RAY BIRCH		NUMBER OF CLASSROOMS ON SITE
INSPECTOR'S TITLE Utility Supervisor		NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE)
TIME OF INSPECTION		WEATHER CONDITION AT TIME OF INSPECTION

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS			B. INTERIOR	C. CLEANLINESS		D. ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL	
		GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOMS	SINKS/FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/SCHOOL GROUNDS	WINDOWS/DOORS/GATES/FENCES
↓ 15	Number of "✓":	15	15	15	11	14	15	15	7	13	15	15	15	15	14	15
	Number of "D":	0	0	0	4	1	0	0	0	2	0	0	0	0	1	0
	Number of "X":	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	Number of N/A's:	0	0	0	0	0	0	0	0	8	0	0	0	0	0	0
Percent of System in Good Repair Number of "✓"s divided by (Total Areas - "NA"s")		100.00%	100.00%	100.00%	73.33%	93.33%	100.00%	100.00%	100.00%	86.67%	100.00%	100.00%	100.00%	100.00%	93.33%	100.00%
Total Percent per Category (average of above)*		100.00%			73.33%	96.67%		100.00%	93.34%		100.00%		100.00%		96.67%	
Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%		GOOD			POOR	GOOD		GOOD	GOOD		GOOD		GOOD		GOOD	

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING: DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE → **95.00%** SCHOOL RATING** → **GOOD**

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75%-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION: _____

PART II: EVALUATION DETAIL		Date of Inspection: 08/16/16				School Name: GUSTINE ELEMENTARY										
AREA	CATEGORY	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
		GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
MEDIA		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
CAFÉ		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
OFFICE		✓	✓	✓	✓	✓	✓	✓	✓	D	✓	✓	✓	✓	✓	✓
	COMMENTS:	The Nurse's office has a leaking faucet.														
LOUNGE		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
PLAYGROUND		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	D	✓
	COMMENTS:	FALL MATERIAL HAS HOLES AND RIPS														
C-6		✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
D-1		✓	✓	✓	✓	✓	✓	✓	NA	D	✓	✓	✓	✓	✓	✓
	COMMENTS:	The water pressure is low at the fountain.														
B-1		✓	✓	✓	D	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:	One of the cabinets is missing a hinge. The transition strip is damaged.														
G-4		✓	✓	✓	D	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:	There are loose hinges at the cabinets.														
G-5		✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
F-5		✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
C-3		✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
R-2		✓	✓	✓	✓	D	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															

PART II: EVALUATION DETAIL Date of Inspection: 08/16/16 School Name: GUSTINE ELEMENTARY

CATEGORY	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
AREA	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
	COMMENTS:	There is storage in the restroom.													
D- RESTROOMS	✓	✓	✓	D	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:	There is peeling paint near the window of the boy's room.													
A- RESTROOMS	✓	✓	✓	D	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:	There is cracked wall tile at the entry of the boys room.													
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														

Marks: ✓ = Good Repair; D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional Area Lines as necessary.